

University of Oregon Lead-Based Paint Activities Guide

Perform all work that impacts lead-based paint or lead-containing paint in strict accordance with all applicable Federal, State, and Local regulations. Applicable regulations will vary based on the project type, building type, and scope of work, and may include (but are not limited to):

- EPA Renovate, Repair, and Painting Program
- OAR 437, Division 2
- OAR 437, Division 3
- HUD Lead-Safe Housing Rule
- University of Oregon Lead Program

Consult with your Owners Representative and EHS for additional information.

Requirements for Collecting, Containerizing, Storing, and Disposing Lead-Based Paint Waste and Debris

Contractor shall collect LBP waste and deposit into waste containers (Figure 1) no less often than at the end of each workday, or as weather requires collection to prevent spread of paint waste and debris.

Contractor shall exercise diligence in not combining Lead-Based Paint waste and debris with non-lead-based paint waste and debris. Plastic sheeting and other barrier/collection material shall be HEPA vacuumed or wet cleaned so that they do not become Lead-Based Paint waste.

Contractor shall keep containers closed except when depositing Lead-Based Paint and debris.

Contractor shall keep all container labels intact and legible (Figure 2), replacing any that become defaced.

Contractor shall, to the extent practicable, keep Lead-Based Paint waste and debris containers, out of the weather and secure by either covering containers with plastic or storing containers inside.

When the waste container is full to arrange a drop-off at our Onyx Bridge office, or a pick-up of material the Contractor shall contact:

Person	Title	Phone	E-mail
Seth Sponcey	Haz Waste Prog Coord.	541-346-2348	ssponcey@uoregon.edu
Jenny Kane	Haz Materials Specialist	541-346-2719	jkan@uoregon.edu
Ben Bythell	Chemical Safety Officer	541-346-0371	bythell@uoregon.edu



Left: Figure 1. An example of a proper lead-based paint waste container. It is in good condition without any holes or punctures and has a sealable lid. 5-gallon buckets are the suggested size as they are easy to secure, cover, and handle. The container should not exceed 40 pounds. Waste containers must be kept closed unless material is being added.

Call (541) 346-2348 to arrange a drop-off of full containers.

Below: Figure 2. An example of a properly filled out hazardous waste label. The label must be legible and contain the word “WASTE”. An indicator as to the contents is also mandatory. In this case, “lead based paint” or “lead based paint debris”. If a label is unavailable, damaged, or defaced, the contractor is allowed to write in sharpie or paint-pen the words “WASTE: Lead Based Paint”. This option is shown in figure 1 to the left. Contractors leave the accumulation start date blank; EHS staff at the Hazardous Waste Facility fill this in.

